

FIG. 1

↑
300-
800 MM
↓




FIG. 2

↑
50-100
MM
↓












FIG. 3









10




FIG. 11

Anisotropic Etch
(e.g. RIE)




FIG. 12




FIG. 13

FIG. 14




FIG. 15




FIG.
16.




FIG.
17




FIG. 18




FIG. 19




FIG. 20




FIG. 21





FIG. 22



9/26

FIG. 23




FIG. 24




FIG. 25




FIG. 26





FIG. 27







FIG.
30




FIG. 31




FIG.
32




FIG.
33




FIG.
34




FIG.
35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41




FIG. 42




FIG. 43





FIG. 44







FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG.51




FIG.52




FIG.53




FIG.54




FIG. 55




FIG. 56

